

8

43-28

Roosevelt Trp

Harold - Dewing

Co Line Road

1918.

LEAF



No. 1201

6	5	4	3	2	1
7	8	9	10	11	12
13	14	15	16	17	18
19	20	21	22	23	24
25	26	27	28	29	30
31	32	33	34	35	36

John Dewing Survey T. 4³ R. 28¹
27

Sat. Aug. 10, 1918

I look over records and
get field notes for Township
43 Range 28.

Sunday. Aug. 11, 1918

John W. Cross, Alma Reed
and I go in Ford to John
Dewings farm. John W. Cross
Reed and I return to back
to Brainerd in Ford from
Dewing and Walter Dewing
I go in Dewings Ford to look
up crew for to work in

Harold J. Cross